

WICHITA FALLS CULTURAL RESOURCES SURVEY
WICHITA COUNTY HERITAGE SOCIETY
SURVEY FORM

No. on Master List: 369

NAME OF SITE: Daniel-DeLee House ADDRESS: 2911 Sturdevant

LEGAL DESCRIPTION: Subdivision #13-part of #12 Morningside Block Lot

PRESENT OWNER Mrs. L. A. DeLee Park North

and MAILING ADDRESS: 2911 Sturdevant

CATEGORY: District ☒ Building Structure Site Object

ORIGINAL USE: residence PRESENT USE residence ~~ZONING~~

PHYSICAL DESCRIPTION: Two story rectangular plan. Hipped roof with intersecting cross gable. Two end chimneys. Difficult to see.

MATERIALS: wall brick roof slate

CONDITION OF EXTERIOR: excellent

ALTERATIONS/ADDITIONS: none discernible

ARCHITECTURAL STYLE/TYPE AND SIGNIFICANCE: English related.

SIGNIFICANT PERSONS AND EVENTS ASSOCIATED WITH SITE: Built 1926; Voelcker & Dixon , architects.

RELATIONSHIP TO SURROUNDINGS: Part of scene.

CURRENT TAX ASSESSMENTS:

Year	Land	Improvements	Total
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>	<u> </u>

PRESENT DESIGNATION:

RECOMMENDED DESIGNATION: National Register Registered Texas Landmark

Local Landmark ☒

If within a district: Significant Contributing ☒ Compatible Intrusion

-2-

OTHER COMMENTS/OBSERVATIONS:

SOURCES OF INFORMATION:

PHOTO DATA: Roll 1 Frame 25RECORDED BY: Ellen Beasley; Susan H. Campbell Date March, 1982

Much of the information above may be transferred directly to survey cards of the Texas Historical Commission. The following information would need to be added, using the THC computer codes, to complete the State cards:

COUNTY: _____ PERIOD: _____
CITY: _____ STYLE: _____
DATE: _____ THEME: _____
CODED SITE NUMBER: _____

EB 8/81



COUNTY QUAD BLOCK 16
CITY Wichita LOT #13-part of #12 MP. NORTH
NAME: Daniel - Delee House
ADDRESS: 2911 Sturdevant

ARCHITECT/BUILDER: Voelcker & Dixon DATE: 1926 PERIOD: 1900 -
OWNER: Mrs. L.A. Delee STYLE: English related (X)
UTM: THEME:

DESCRIPTION: Two story rectangular plan. Hipped roof with intersecting cross gable. Two end chimneys

BUILDING MATERIAL: wall: Brick roof: Shale
PHYSICAL CONDITION: Excellent SITE: original ☒ or moved date
ALTERATIONS: none discernible
SIGNIFICANCE: Built 1926; Voelcker Voelcker & Dixon, architects

AREA OF SIGNIFICANCE: LEVEL OF SIGNIFICANCE:
DESIGNATION: NR NHL RTHL HABS HAER HESI OTHER:
ORIGINAL USE: Residence PRESENT USE: Residence
RELATIONSHIP TO SURROUNDINGS:
ACREAGE/BOUNDARY DESCRIPTION:

BIBLIOGRAPHIC DATA:
SEE INFO/CORRESPONDENCE FILES:
RECORDED BY: Susan H. Campbell INFORMANT: OWNER
DATE: PHOTO DATA: